

[illegible]

1. BUILDING NAME (Common)		(Historic)	
Faith Congregational Church		Windsor Ave Congregational Church 317 by whom Church	
2. TOWN/CITY	VILLAGE	COUNTY	
Hartford		Hartford	
3. STREET AND NUMBER (and/or location)			
2030 Main St			
4. OWNER(S)			
Name of Person & mailing address or onto Constitution		☐ Public	☒ Private
5. USE (Present)			
Religious (Historic)			
6. ACCESSIBILITY TO PUBLIC:		EXTERIOR VISIBLE FROM PUBLIC ROAD	INTERIOR ACCESSIBLE
☒ Yes ☐ No		☒ Yes ☐ No	IF YES EXPLAIN
		DATE OF CONSTRUCTION	
		1871 site acquired 1905 fund.	

TO PUBLIC: ☐ ☒ ☐

7. STYLE OF BUILDING Romanesque Revival / High Victorian Gothic

DATE OF CONSTRUCTION 1871 ^{complete} 1904 ^{circ}

8. MATERIAL(S) (Indicate use or location when appropriate)

☐ Clapboard ☐ Asbestos Siding ☒ Brick ☐ Other (Specify) _____

☐ Wood Shingle ☐ Asphalt Siding ☐ Fieldstone Ohio stone trimmed

☐ Board & Batten ☐ Stucco ☐ Cobblestone red brick

☐ Aluminum Siding ☐ Concrete Type: _____ ☐ Cut stone Type: _____

9. STRUCTURAL SYSTEM

☐ Wood frame ☐ Post and beam ☐ balloon

☒ Load bearing masonry ☐ Structural iron or steel

☐ Other (Specify) _____

Site

10. ROOF (Type)

☐ Gable	☐ Flat	☐ Mansard	☐ Monitor	☐ sawtooth
☒ Gambrel	☐ Shed	☐ Hip	☐ Round	☒ Other (Specify) <u>intersect</u>

(Material)

☐ Wood Shingle	☐ Roll Asphalt	☐ Tin	☒ Slate
☐ Asphalt shingle	☐ Built up	☐ Tile	☐ Other (Specify) _____

Research?

Keep? (6/8/20)

11. NUMBER OF STORIES ☐ APPROXIMATE DIMENSIONS

12. CONDITION (Structural) (Exterior)

☐ Excellent ☒ Good ☐ Fair ☐ Deteriorated ☐ Excellent ☒ Good ☐ Fair ☐ Deteriorated

IF YES, EXPLAIN

13. INTEGRITY (Location)	WHEN ?	(Alterations)	IF YES, EXPLAIN
☒ On original site ☐ Moved		☒ Yes ☐ No	addition parish house 19
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES			

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

☐ Barn	☐ Shed	☐ Garage	☐ Other landscape features or buildings (Specify)
☐ Carriage house	☐ Shop	☐ Garden	N/A

15. SURROUNDING ENVIRONMENT

☐ Open land	☐ Wood-land	☐ Residential	☐ Scattered buildings visible from site
☐ Commercial	☐ Indus-trial	☐ Rural	☒ High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS *directly across from Cemetery*
Other types of bldg around Cemetery - apt - (OVER)

(OVER)

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
(203) 566-3005

Town No.:	Site No.:
UTM	
QUAD:	
DISTRICT	IF NR, SPECIFY
☐ S ☐ NR	☐ Actual ☐ Potential

IDENTIFICATION

1. BUILDING NAME (Common)	(Historic)
Faith Congregational Church	Pavilion Congregational Church
2. TOWN/CITY	VILLAGE
Hartford	Hartford
3. STREET AND NUMBER (and/or location)	
2030 Main Street Hartford, Connecticut	
4. OWNER(S)	
Name of Person & mailing address or onto Continuation sheet	☐ Public ☒ Private
5. USE (Present)	(Historic)

DESCRIPTION

6. ACCESSIBILITY TO PUBLIC:	EXTERIOR VISIBLE FROM PUBLIC ROAD	INTERIOR ACCESSIBLE	IF YES, EXPLAIN
☒ Yes ☐ No	☒ Yes ☐ No	☒ Yes ☐ No	
7. STYLE OF BUILDING			DATE OF CONSTRUCTION
Romantic Revival / High Victorian Gothic			1871 cr. / 1904 cr.
8. MATERIAL(S) (Indicate use or location when appropriate)			
☐ Clapboard	☐ Asbestos Siding	☒ Brick	☐ Other (Specify)
☐ Wood Shingle	☐ Asphalt Siding	☐ Fieldstone	
☐ Board & Batten	☐ Stucco	☐ Cobblestone	
☐ Aluminum Siding	☐ Concrete Type:	☐ Cut stone Type:	
9. STRUCTURAL SYSTEM			
☐ Wood frame	☐ Post and beam	☐ balloon	
☒ Load bearing masonry		☐ Structural iron or steel	
☐ Other (Specify)			
10. ROOF (Type)			
☐ Gable	☐ Flat	☐ Mansard	☐ Monitor
☒ Gambrel	☐ Shed	☐ Hip	☐ Round
(Material)			☒ Other (Specify) intersecting
☐ Wood Shingle	☐ Roll Asphalt	☐ Tin	☐ Slate
☐ Asphalt shingle	☐ Built up	☐ Tile	☐ Other (Specify)
11. NUMBER OF STORIES			
APPROXIMATE DIMENSIONS			
12. CONDITION (Structural)			
☐ Excellent	☒ Good	☐ Fair	☐ Deteriorated
(Exterior)			
☐ Excellent	☒ Good	☐ Fair	☐ Deteriorated
13. INTEGRITY (Location)			
☒ On original site	☐ Moved	WHEN ?	(Alterations)
☒ Yes	☐ No		addition - parsonage 1904
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES			
☐ Barn	☐ Shed	☐ Garage	☐ Other landscape features or buildings (Specify)
☐ Carriage house	☐ Shop	☐ Garden	N/A
15. SURROUNDING ENVIRONMENT			
☐ Open land	☐ Wood-land	☐ Residential	☐ Scattered buildings visible from site
☐ Commercial	☐ Indus-trial	☐ Rural	☒ High building density
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS			

Other types of bldg around
Cemetery - apt -

(OVER)

Describe ① exterior
bldg & ② interior
parish house
Whole church
& parish house

18. ARCHITECT

S J F Thayer of Boston

BUILDER

19. HISTORICAL OR ARCHITECTURAL IMPORTANCE

Quality
of
architecture① Historical
background
start
who or
historical
development

How does
this
structure
compare
to other
church
bldgs
in HHA.

in terms
of other
churches
in
HHA
How
compare

How does
it compare?
Where
does
it stand

Church
1860-1880
in
HHA

SIGNIFICANCE

SOURCES

PHOTOGRAPHER

DATE

VIEW

NEGATIVE ON FILE

NAME

DATE

ORGANIZATION

ADDRESS

Place

Photograph

Here

20. SUBSEQUENT FIELD EVALUATIONS

21. THREATS TO BUILDING OR SITE

☒ None known ☐ Highways ☐ Vandalism ☐ Developers ☐ Other _____

☐ Renewal ☐ Private ☐ Deterioration ☐ Zoning ☐ Explanation _____